

FORTY-FIFTH
ANNUAL REPORT

OF THE

Medical Officer of Health

ON THE

VITAL AND SANITARY CONDITION

OF THE

Metropolitan Borough of St. Pancras, London.

REPORT FOR THE YEAR 1900.

BY

JOHN F. J. SYKES, M.D., D.Sc.

TABLE 13.

INTIMATIONS as to Nuisances served by Sanitary Inspectors during the Fifty-two Weeks ended 29th December, 1900.

Nuisances.	Districts and Inspectors.	N. 1, 2. G. R.	N. 3, 4, 5. H. N.	E. 1, 2, 3. J. O.	E. 1, 2, 3. C. H. J.	E. 4, 5. W. B.	W. 1, 2. H. G. W.	W. 3, 4, 5. J. I. L.	S. 1, 2, 3. C. W.	S. 1, 2, 3. H. R. C.	S. 4, 5. J. L.	Tenement Houses.		Workplaces.		Food.			TOTALS
												N. & E.	W. & S.	Men. F. A. B.	Women. A. J. S.	N. & E. W. G. A.	W. & S. H. J. W.	W. & S. J. O.	
1 The house or part of the house in a dirty condition		10	46	1	3	73	21	84	15	26	47	—	—	13	8	—	—	—	347
2 The house or part of the house in a damp condition		4	—	4	4	6	17	15	—	19	4	—	—	4	8	—	—	—	85
3 The house in a dilapidated condition		4	33	—	—	15	18	28	—	12	5	—	—	2	2	—	—	—	119
4 The inlet of surface drain improperly trapped		8	—	1	4	20	16	35	—	16	1	—	—	6	1	—	—	—	108
5 The water-closet so foul as to be a nuisance		7	3	2	9	36	29	28	3	37	28	—	—	27	4	—	—	—	213
6 " " without a water supply		13	11	4	5	15	17	20	4	16	29	—	—	15	1	—	—	—	150
7 " " with a deficient supply of water		10	20	1	12	28	2	14	1	11	11	—	—	10	1	—	—	—	121
8 " " improperly constructed so as to be a nuisance		2	1	1	14	7	14	23	—	—	3	—	—	2	—	—	—	—	67
9 " " so defective as to be a nuisance		23	11	4	13	58	29	44	1	47	23	—	—	24	9	—	—	—	286
10 " " stopped		7	2	4	2	20	8	14	2	25	20	—	—	16	—	—	—	—	120
11 " " placed in an improper position		—	—	—	1	4	—	5	—	—	—	—	—	3	—	—	—	—	13
12 Insufficient external ventilation to water-closet		1	—	1	1	2	—	7	—	25	4	—	—	1	1	—	—	—	43
13 Insufficient water-closet accommodation		11	5	—	3	9	—	16	6	16	51	—	—	15	4	—	—	—	136
14 The soil-pipe defective		29	—	—	6	7	1	6	—	11	10	—	—	2	—	—	—	—	72
15 " " unventilated		9	—	—	10	1	—	5	—	16	1	—	—	—	1	—	—	—	43
16 " " improperly ventilated		16	2	—	1	—	—	9	—	3	—	—	—	—	—	—	—	—	31
17 The yard in a condition injurious to health by reason of the want of proper paving		32	20	—	3	42	9	61	1	43	5	—	—	6	—	—	—	—	222
18 " " dirty		4	2	—	2	9	10	78	3	23	4	—	—	1	—	—	—	—	136
19 " " undrained		1	2	—	1	—	—	3	—	3	—	—	—	1	—	—	—	—	8
20 A gully trap improperly placed within the house		1	—	—	7	2	—	3	—	3	—	—	—	1	—	—	—	—	17
21 The waste-pipe of sink directly connected with the drain		19	4	1	7	15	27	10	—	14	13	—	—	3	—	—	—	—	113
22 " " " improperly trapped		—	—	—	1	6	—	1	—	—	—	—	—	—	—	—	—	—	8
23 " " " untrapped		1	1	2	—	1	1	—	—	—	1	—	—	—	—	—	—	—	8
24 " " of lavatory directly connected with the drain		—	—	—	—	—	—	2	—	1	1	—	—	—	—	—	—	—	4
25 " " " improperly trapped		—	—	—	—	1	—	—	—	—	2	—	—	—	—	—	—	—	3
26 " " " untrapped		—	—	—	1	—	—	—	—	—	—	—	—	—	—	—	—	—	1
27 " " of bath directly connected with the drain		—	—	—	—	—	—	4	—	—	—	—	—	—	—	—	—	—	4
28 " " " improperly trapped		—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
29 " " " untrapped		—	1	—	1	—	—	—	—	—	—	—	—	—	—	—	—	—	2
30 The water cistern so foul as to be a nuisance		1	—	—	—	6	9	13	1	2	5	—	—	—	—	—	—	—	37
31 " " being without a close-fitting cover		3	1	—	2	7	12	13	—	2	12	—	—	—	1	—	—	—	53
32 " " being placed in an improper position		—	1	1	—	1	—	—	—	1	—	—	—	—	—	—	—	—	4
33 " " defective		—	2	—	—	5	24	1	—	—	2	—	—	—	—	—	—	—	34
Carried forward		216	168	27	113	396	264	542	37	369	282	—	—	153	41	—	—	—	2608

List VI.

ST. PANCRAS, LONDON.

BAKEHOUSES, end of 1900.

(The diagram referred to was published in the Annual Report for 1896.)

No. on Diagram.	Consecutive No.	Situations, Divisions, and Sub-Divisions.	Name of Occupier.	Distance of floor above or below ground level.	Distance of ceiling above or below ground level.
NORTH DIVISION.					
1.—Highgate.					
16	1	134, Fortess Road	P. Gotfries & Sons ..	Level ..	8ft. 2in. above.
10	2	49, Leverton Street	G. E. Moir	Level ..	8ft. 6in. „
17	3	60, Chetwynd Road	J. Wilson	Level ..	8ft. „
100	4	121, Dartmouth Park Hill ..	John Leister	7ft. 6in. below	Level.
58	5	151, „ „	James Hudson	6ft. 6in. „	„
88	6	9, Retcar Street	Frank Malan	7ft. 3in. „	6in. below.
179	7	4, South Grove	Horsley & Son	Level and one	10in. „
14	7A	„ „	„ „	8ft. 6in. below ground	8ft. 3in. above.
95	8	37, York Rise	John A. Skinner ..	7ft. 6in. below	1ft. 2in. „
2.—St. John's Park.					
157	9	93, Leighton Road	Not in use	8ft. below ..	6in. below.
135	10	99, Brecknock Road	Mr. Sconce	8ft. „ ..	Level.
158	11	68, Falkland Road	Frost Bros.	8ft. „ ..	6in. below.
136	12	47, Fortess Road	E. Parker	8ft. 6in. below	Level.
48	13	7, Willow Walk, or 11, Fortess Road	F. Lister	One 6ft. and one 2ft. below	2ft. 3in. above.
36	13A	„	„	„	5ft. 3in. „
3.—Gospel Oak.					
36A	13B	21, Rochford Street	Not in use	2ft. 2in. below	6ft. 9in. above.
101	14	101, Allcroft Road	Anton Blesser	7ft. 6in. below	Level.
4	15	45, Ashdown Street	Not in use	Level ..	10ft. above.
26	16	108, Carlton Street	Peter Schneider ..	Level ..	7ft. 6in. „
20	17	55, Haverstock Road	Lepold Orth	Level ..	7ft. 6in. „
21	18	63, Highgate Road	W. H. J. Mortimer ..	Level ..	7ft. 6in. „
49	19	141, „ „	Francis Paterson ..	6ft. below ..	1ft. 6in. „
28	20	2, Lamble Street	P. Müller	Level ..	7ft. 2in. „
5	21	10, Lismore Circus	H. Stubenhagen ..	Level ..	9ft. 6in. „
56	22	3, Mansfield Road	Not in use	6ft. 6in. below	6 in. „
6	23	66, „ „	Joachim Peters ..	Level ..	9ft. „
177	24	163, Queen's Crescent ..	Richard Filby & Son ..	8ft. 6in. below	6in. below.
54	25	167, „ „	„	6ft. 6in. below	1ft. 6in. above.
18	26	160, Weedington Road ..	G. Thorogood	Level ..	8ft. „
119	27	37, Wellesley Road	„	7ft. 6in. below	6in. below.